


Barlow C of E VC Primary School



Tangled Lynx




4



Site View



3,5,7



● = Existing Trees



1



4

5

Wigwam Frame



playground
equipment
specialists

Ref: SO45738 Pages: 1/2 Date: 18/05/22 Drawing 1 Designer HC

Please Note:
All works are subject to a further pre-install site survey to determine the exact measurements and condition of the area. Existing markings and equipment have been shown for design purposes only.
We have costed for removal works - see quotation.

Barlow C of E VC Primary School

Tree Trail - Thicket



Site View



6+7



3,5,7



Spinning Log


Stepping Logs

Balance Beam

Rope Traverse

6

7



2+3

4+5

6+7

1

● = Existing Trees



6+7



Please Note:
All works are subject to a further pre-install site survey to determine the exact measurements and condition of the area. Existing markings and equipment have been shown for design purposes only.
We have costed for removal works - see quotation.



playground
equipment
specialists